

Quick Reference Guide

Version 1.02

COOLMUSCLE - RT3

K parameters



www.rpmechatronics.co.uk

| K # | Description | Unit | Values |
|-----|---|--|---|
| K20 | UART0 baud rate | Kbits | 0:38.4, 1:9.6, 2:19.2, 3:57.6 10:13->modbus, 10:38.4, 11:9.6, 12:19.2, 13:57.6 |
| K21 | Semi/full closed loop | 0.1 deg | 0: Full closed loop 1-36: vector angle |
| K22 | Time delay for semi closed loop | msec | min: 10 max: 1000 |
| K23 | Event status | N/A | 0: Polling only 1: All alarm and motor status codes 2: Input status 4: Output status 8: Disable echo 16: Enable warnings and messages 32: Merge event - "Mx". |
| K24 | Timed trigger and quadrature output interval (see K34) | pulses | min: 10 max: 32767 |
| K25 | Time delay for slow signal response | 0.1 sec | min: 1 max: 9 |
| K26 | Invert input signal | 0: True 1: False | |
| K27 | Input function at target voltage level of Quick Response Signal | 0: No Action 1: General Use 2: Origin Sensor 3: Manual Feed CW 4: Manual Feed CCW 5: Output Index signal not Inposition Signal 6: CW limit switch and origin switch 7: Emergency Stop 8: Full Stop 9: CCW Limit and origin switch | |
| K28 | Input function at the rising edge of Quick Response Signal | 0: No Action 1: Alarm reset/Pause 2: Motor Free 3: Reset Counter 4: Execute Next Step 5: Execute Previous Step 6: Execute Bank 1 7: Go Origin 8: Jog CW (Execute Bank 2 when K36=2) 9: Jog CCW (Execute Bank 3 when K36=2) | |
| K29 | Input function at the falling edge of Quick Response Signal | 5 same Functions as K28 except 2: Enable Motor | |
| K30 | Input function at target voltage level of Slow Response Signal | 5 same Functions as K27 | |
| K31 | Input function at the rising edge of Slow Response Signal | 5 same Functions as K28 | |
| K32 | Input function at the falling edge of Slow Response Signal | 5 same Functions as K28 except 2: Enable Motor | |
| K33 | Output Logic | 0: Normally open 1: Normally closed | |
| K34 | Output function | 0: Command 1: Inposition 2: Alarm 3: CW Limit O1/F1 4: CW Limit O2/F2 5: Analog Output 6: Output on completion of Origin Search 7: Timed Trigger 8: Quadrature output/motor free** 9: Torque Limit reached - Push Mode Only *Quadrature output if both outputs set to 8 (E.g. K34=88) **motor free if one output is set to 8. (E.g. K34=80) | |
| K35 | Analog output function | 0: Target position 1: Target position magnified by 8 2: Current Position 3: Current Position magnified by 8 4: Position Error 5: Position Error magnified by 8 6: Current Velocity/16 7: Current Velocity/2 8: I q Real 9: Iq*8 | |

| K # | Description | Unit | Values |
|-----|---|--|--|
| K55 | Inposition tolerance | Pulses | Min: 1 Max: 1000 |
| K56 | Overflow alarm level | Kpulses | Min: 1 Max: 32767 |
| K57 | Overload alarm time delay | msec | Min: 100 Max: 10000 |
| K58 | Software Limit (+) | 100 pulses | Min: 0 (Off) Max: 32767 |
| K59 | Software Limit (-) | 100 pulses | Min: -32767 Max: 0 (Off) |
| K60 | Push mode current level | % | Min: 10 Max: 80 NOTE: push mode % is based on 80% of full torque |
| K61 | Push time | msec | Min: 1 Max: 50001 (infinite push) |
| K62 | RS-485 Node ID | 0: RS-232 mode 1-256: RS-485 ID -1~-256: RS-485 Node ID, no auto report function NOTE: set K65 first when using Modbus | |
| K63 | External encoder input | 0: None 1: Phase A only 2: Phase A and B 3: Enable "Fx" and "Cx" variables | |
| K64 | Analog input function | 0: None, 1:5.0, 2: P.0, 3:5.13, 4: P.24 5: S.14, 6: P.25, 7: S. speed 0-5 et speed 8: Position Multiplier 9: Analog control only (K38) NOTE: see documentation on logic banks for complete control with analog input | |
| K65 | Slave motor Baud Rate Set master motor only | Kbits | 0:38.4, 1:9.6 2:19.2, 3:57.6 4:76.8, 5:129 6:173, 7:515 10:38.4, 11:9.6, 12:19.2, 13:57.6 14:76.8, 15:129, 16:173, 17:515 |
| K66 | Data Streaming | 0: None 1: Send back speed target 2: Send back real position 3: Send back real speed 4: Send back real current Iq 5: Position Real 6: Velocity Real 0-3000 | |
| K67 | Data Streaming sample timing | msec | 0: S Curve with fixed timing 1: S Curve without timing |
| K68 | S Curve Function | 0-1024 | |
| K69 | S Curve Gain | 0-1024 | |
| K70 | Send carriage return | 0: No line feed after carriage return 1: Line feed after carriage return | |
| K71 | Temperature limit | Deg C | Min: 0 Max: 150 |
| K72 | Regeneration voltage return level | 0.1V | Min: 0 Max: 391 |
| K73 | Merge motion output signal length | msec | Min: 1 Max: 1000 |
| K74 | External Torque feedback P-Gain | Max: 1000 | |
| K75 | External Torque feedback I-Gain | Max: 500 | |
| K77 | External Torque feedback mean value | Max: 10.24 | |
| K78 | External Torque feedback Gain | Max: 10.24 | |
| K85 | Logic bank number to start on powerup | Min: 0 (no bank) Max: 30 | |
| K86 | Coordinate motion - Synchronize motors | 0: Off 1: On | |
| K87 | Logic bank scan period | msec | Min: 1 Max: 32767 |
| K88 | External encoder resolution | Max: 50000 | |
| K89 | Modbus input register address | Max: 65535 | |
| K90 | Modbus output register address | Max: 65535 | |

Quick Reference Guide

Version 1.02

COOLMUSCLE - RT3

CML List




www.rpmechatronics.co.uk

| Command | Function | Example |
|--------------|--|---|
| P, S, A0, M0 | Dynamic commands Position, Speed, Acceleration and Torque | P0=1000, S0=200 A0=10, M0=75 |
| A | Dynamic command execution is running. | |
| n | Dynamic command execution n=1 to 8 | P3=2000, S3=100, A3=100 A3 |
| P | Position (pulses) | P1=2500 |
| S | Speed (see K37 for unit) | S1=1000 |
| S1-S15 | Acceleration (Kpps/2) | S2=200 |
| A | Torque limit (% full torque) | A1=250 A2=500 |
| M | Emergency stop on all motors (0-100%) | M0=100 |
| M1-M8 | Emergency stop on all motors (0-100%) | M1=10 |
| T | Timer (msec) | T1=100 |
| T1-T8 | Radius - Coordinated motion | T2=300 |
| R | Center point - coordinated motion | R5.1=50, R5.2=50 (circle) R5.1=70, R5.2=100 (ellipse) |
| N1-R25 | Variable Variables are used in all banks. They can be assigned an internal state in the motor or an integer or string. See RT3 - Banks manual for details | N1=500 N12=30 V1="Px" (current position) V1="Sx" (current speed) V1="Ix" (current iq value) V1="Ux" (current motor status) V1="Pe" (current position error) V1="Pt" (target position) V1="An4" (analog input 4 - 0-1023) V1="St" (target speed) V1="Fx" (Input 2 frequency) V1="Cx" (Input 2 counter) V1="What" (string type - 4 char max) V1=1976 (long integer type) |
| U | Advanced math function See RT3 - Banks manual for details | U1 - sine U2 - cosine U3 - square root U4 - lookup table U5 - polynomial N U6 - polynomial R |
| B # | Program Bank | B1, A1, P1 |
| END | Logic Bank | END |
| L # | Clear all program banks | S0=V1*S1 END |
| B 100 | Execute logic bank | |
| L 100 | Execute next line in program bank | |
| L | Execute previous line in program bank | |
| < | Stop logic bank | |
| J 1 | Pause motor (all motors on a daisy chain) Pause only that motor on a daisy chain Note: To not only stop the motor but completely stop a program bank send the pause command twice with a carriage return or comma between. | J1, 2 e.g. 1] e.g. 2], |
| * | Emergency stop on all motors | |
| † | Emergency stop on all motors | |
| ‡ | Stop after current motion | |
| C | Call program bank (used only in program banks) | B1, A1, P1 END C3 |
| CL | Call logic bank (used only in logic banks) | L1 END L3 |
| J | Jump program bank (used only in program banks) | B1 J2 END J3 |
| JL | Jump logic bank (used only in logic banks) | JL1 END JL1 |
| O | Output High | O1 |
| F | Output Low | F1 |
| I | Input Status | I2, C2, C3 |

| Command | Function | Example |
|---------|--|--|
| X | Loop | X25 |
| X- | max 255 nested loops allowed | S1, A1, P1+ X25- |
| Y | P without wait | B1 S1, A1, Y1, Y1.1 P2.2 END |
| Q | Push mode (Q is set in P) | A1, 1, S1, 1, Z1, 1 P2.2 |
| Z | Q without wait | S1, A1, O1 |
| T0 | No action | I3, C2, T0 |
| W0 | wait | P=50 |
| ~ | Continuous Point motion (CP motion) Note: P is assigned at the full resolution of 50,000 ppr. | ... |
| (bar) | Origin Search | Origin Search |
| | 1 - Go to position 0 | |
| | 2 - Set the current position to 0 | |
| | Enable Motor | |
| | Disable Motor | |
| S | Save to EEPROM | |
| D | Set Node ID in R5:485 Did=serial number | D3=103490138 S ets motor with serial number 103490138 to ID3 |
| [0 | Open RS485 communication to all nodes (n where n=1-255. | |
| [n | Address node with ID n. Only node n will communicate until (0 is issued. | |
| ? | Query | |

Wiring Diagram



| Standard motor cable | Function | Description | Usage |
|----------------------|-----------|-----------------------------------|----------------------------|
| 1 | +24VDC IN | Motor Power | |
| 2 | GROUND 1 | Power in return | |
| 3 | INPUT 2- | Return for pin 9 | CCW-, Direction-Serial 2 |
| 4 | OUTPUT 2 | Digital Output, 5 serial Tx | Serial 1 |
| 5 | OUTPUT 1 | Digital Output, 5 serial Tx | V+ |
| 6 | INPUT 4 | Digital Input, Analog Input | |
| 7 | INPUT 3 | Digital Input | |
| 8 | INPUT 1- | Return for pin 10 | CCW+, 5 step |
| 9 | INPUT 2+ | Digital Input, Pulse, Counter, Rx | CCW+, Direction+, Serial 2 |
| 10 | INPUT 1+ | Digital Input, Pulse, Counter, Rx | CCW+, 5 step+, Serial 1 |
| 11 | GROUND 1 | Signal ground | V- |
| 12 | +5VDC OUT | Power out (50mA max) | |